

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 2

Sewershed: Gwynns Falls

Company: Savin

Date: 9/8/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S04CC1017MH

Test ID: D1032-027014

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S04CC1017MH
7			Dye Test Visible	DYE SEEN AT JOINT
10			Dye Test Visible	DYE SEEN AT JOINT
12.89999962			Dye Test Visible	DYE SEEN AT JOINT
15.5			Dye Test Visible	DYE SEEN AT JOINT
19.29999924			Dye Test Visible	DYE SEEN AT JOINT
22.10000038			Dye Test Visible	DYE SEEN AT JOINT
25.29999924			Dye Test Visible	DYE SEEN AT JOINT
28.20000076			Dye Test Visible	DYE SEEN AT JOINT
31.10000038			Dye Test Visible	DYE SEEN AT JOINT

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 2
Sewershed: <u>Gwynns Falls</u>	Company: <u>Savin</u>	Date: <u>9/8/2009</u>
Test to be performed: Smoke <input type="checkbox"/> Dyed Water <input checked="" type="checkbox"/>	Ground Condition: Dry <input checked="" type="checkbox"/> Damp <input type="checkbox"/> Wet <input type="checkbox"/>	Supervisor: <u>JAW</u>
Manhole_ID: <u>S04CC1017MH</u>	Test ID: <u>D1032-027014</u>	Notification Made: <u>NA</u> (Residents, Fire, 311)
34.29999924	Dye Test Visible	DYE SEEN AT JOINT
37.70000076	Dye Test Visible	DYE SEEN AT JOINT
57.59999847	Abandoned Survey	DYE TEST COMPLETE